

Annexure D

BUILDING SAFETY CERTIFICATE

No. 307

Dated: 16.09.2026

It is certified that the existing building ST. FRANCIS CONVENT HR SEC SCHOOL (name of the building or premises) at ST. FRANCIS CONVENT HR SEC SCHOOL RAISEN

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+4	G+2	G+2	G+2		

The building is owned/occupied by SOCIETY OF SISTERS OF ST. FRANCIS RAISEN (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD Sub Division Raisen (Name of Department/ Govt.) on 16.09.26 (date of inspection) in the presence of Principal ST. FRANCIS CONVENT HR SEC SCHOOL RAISEN (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16.09.26 for a period of 15.09.27 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Good Condition (Block 1)
2. Good Condition (Block 2)
3. Good Condition (Block 3)
4. Good Condition (Block 4)

Issued on 16.09.2026 at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: Sub Divisional Officer
Name: P.W.D. Sub Division, Raisen

Designation: Sub Divisional Officer
Name & Address of Department/ Office: P.W.D. Sub Division, Raisen

Saman
Sub. Engineer
PWD Sub Div Raisen
Raisen

Principal
St. Francis Convent
Hr Sec. School
Raisen (M.P.)

Executive Engineer
P.W.D. Division Raisen - (M.P.)
Manager
St. Francis Convent Hr. Sec. School
Raisen (M.P.)